

FIG.1




FIG.2




FIG.3




FIG.4




FIG. 5

[illegible]

FIG.6

		WASHING ABILITY OF ANALYZER		
		OK	GOOD	EXCELLENT
LEVEL OF INFLUENCE OF CROSS-CONTAMINATION	LOW	ADDITIONAL WASHING	NO ADDITIONAL WASHING	NO ADDITIONAL WASHING
	MIDDLE	ADDITIONAL WASHING	ADDITIONAL WASHING	NO ADDITIONAL WASHING
	HIGH	ADDITIONAL WASHING	ADDITIONAL WASHING	ADDITIONAL WASHING

FIG.7

50

ALARM		
CODE	LEVEL	ALARM
101-4	CAUTION	CHECK REAGENT CROSS-CONTAMINATION!
		12:45
101-8	CAUTION	CHECK REAGENT CROSS-CONTAMINATION!
		12:46

51

DETAIL

A REAGENT CROSS-CONTAMINATION MAY OCCUR BETWEEN 4Ch.Mg AND 8Ch. ALP. PLEASE CARRY OUT EVASION REGISTRATION

CLOSE

TO NEXT

52

53

FIG.8

PLEASE CHECK TO ☐ OF THE PAIR WHICH PRESENTS CROSS-CONTAMINATION

	OFFENSIVE TEST			DEFENSIVE TEST			
	No.	TEST NAME	REAGENT MANUFACTURER	REAGENT TYPE	TEST NAME	REAGENT MANUFACTURER	REAGENT TYPE
<input type="checkbox"/>	1	ALP	A	R1	Mg	B	R1
<input type="checkbox"/>	2	TG	C	R1	Lip	D	R1

54

57

58

59

60

61

62

55

56

YES

CLOSE

FIG.9




FIG.10




FIG.11




FIG.12




FIG.13

